

1970
 COUGAR
 Right Rear

5/16" ID HOLE IN
 REINFORCING

1/4" thick
 reinf. frame rail
 inside frame rail

Existing 3/8 to 7/16
 holes on 3" center

Approx factory
 Tail Pipe bracket

Easy mount bracket
 with existing hole
 however, into rear
 w/ dual exhaust
 tail pipes

~1 1/4" all over
 weight on this
 side
 ~7" axle hanging
 ~3 3/8" w/ weight on

Base extends into
 sway bar path

Top of Leaf Spring

